




UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION III
Environmental Sciences Center
701 Mapes Road
Fort Meade, Maryland 20755-5350

DATE : March 7, 2012

SUBJECT: Region III Data QA Review

FROM: Colleen Walling 
Region III ESAT RPO (3EA20)

TO: Rich Fetzer
Remedial Project Manager (3HS31)

Attached is the organic data validation report for the Dimock Residential Groundwater site (DAS:# R33917; SDG: #480-16127-1) completed by the Region III Environmental Services Assistance Team (ESAT) contractor under the direction of Region III EAID.


If you have any questions regarding this review, please call me at (410) 305-2763.

Attachment

TO: #0042 TDF: 03014 Data Validation
TO: #0042 TDF: #02085 Sample log-in processing

cc: Gene Nance (Techlaw)
Suddha Graves (Techlaw)

OFFICE OF ANALYTICAL SERVICES AND QUALITY ASSURANCE

 Printed on 100% recycled/recyclable paper with 100% post-consumer fiber and process chlorine free.
Customer Service Hotline: 1-800-438-2474

ESAT DATA VALIDATION EVALUATION CHECKLIST

Contract # EP-W-06-016

ckw 3/7/12

0042

TDF# 02085 - Sample log in process

Task Order #: 0042 TDF #: 03014 Revision #: 0 Case/DAS #: R33917
 Site Name: Dimock SDG #: 480-16217-1
 Analysis Type: Organic SOW #: SW-846 Method 8015B
 Review: Ex. 4 - CBI
 CLP Laboratory Code: TAL BUF

EPA CLP TPO: Jennifer Feranda

Region: 2

EPA RPM:

cc:

Number of hours spent on review: 2

Number of samples: 13

Validation Type: M3

Flat File Required Yes No

Date submitted to EPA: 3/7/12

CRITERIA	YES	NO	COMMENTS
Format according to Region III protocol	✓	—	
Clarity of report	✓	—	
Qualifiers applied correctly	✓	—	
Consistency between narrative and data summary form(s)	✓	—	
Error-free transcription	✓	—	

EFFICIENCY OF CONTRACTOR	YES	NO	COMMENTS
Approval recommended for current submission	✓	—	
Time spent on review is reasonable	✓	—	
Technical Evaluation	4.0	—	Jamael A. Burma 3/7/2012 EPA Oversight

ESD OVERSIGHT

DATES

Received at EPA
 Oversight assigned
 Oversight received
 Oversight completed
 Feedback given
 Mailed to RPM

EPA

3/7/2012 (ckw)
 3/7/2012

Oversight

J.A.B.
 3/7/2012
 3/7/2012

ESAT

SD 3/7/12
 posted to J. d. ra

Environmental Protection Agency
Office of Emergency and Remedial Response
TECHNICAL DIRECTION FORM
REGION 3 - ESAT

Contract No.: EP-W-06-016
Contractor Lockheed
Task Order No.: 0042
Sub-Task No.: 2
Technical Direction No. 03014

Task Order Project Officer: Colleen Walling

Phone (410) 305-2763

Description of Task: Data Review
Account Number: 2012T03N303DC6A3TARS00
Deliverable Due Date: 03/07/2012

SITE NAME: DIMOCK RESIDENTIAL GROUNDWATER SITE

SDG: 480-16217-1

Review the CLP analytical data for case: R33917

Additional sample information can be found on the attached QA assignment slip.

Follow data validation procedures outlined in SOPs and Guidance documents listed in the Task Order.

Case: R33917
Number of Samples: 13 Water
Validation Level: M3
Comments: FLAT FILE REQ'D: YES--DATA VALIDATION--02085 SAMPLE LOG-IN PROCESSING

I CERTIFY THAT THIS TECHNICAL DIRECTIVE DOES NOT REQUEST SERVICES THAT ARE INHERENTLY GOVERNMENTAL FUNCTIONS AND THAT IT DOES NOT ALTER THE (1) STATEMENT OF WORK, (2) LEVEL OF EFFORT, (3) COST OF PERFORMING THE AUTHORIZED WORK, (4) NUMBER OF DELIVERABLES, OR (5) THE DUE DATES OF DELIVERABLES FOR THE ABOVE REFERENCED WORK ASSIGNMENT

TOPO Signature Colleen Walling

Date 3/7/2012

Original to Contractor
cc: TOPO file

Project Officer

Contracting Officer